

<b>Product Name:</b>	HPL – 547 EXPRESSCARD	
	547-5W1F-HOST CONNECTORS SYSTEMS	
<b>Product Manager:</b>	Jimmy Wang	
<b>Subject:</b>	Notification of Planned Change	
<b>Distribution:</b>	Affected customers	
<b>Type of Change:</b>	End-of-Life	
<b>Change Description:</b>	End of life of part numbers	
<b>Reason for Change:</b>	Declined product sales	
<b>Affected Parts:</b>	10053826-100ABTLF, 10053826-200ABSMLF, 10053827-00ALF, 10065483-00ALF, 10070469-001LF, 10070470-001LF	
<b>Effective Date of Change:</b>	30 October ,2023	
<b>Last Time Buy Date:</b>	31 March ,2023	
<b>Earliest Disty Return Date:</b>	31 January ,2023	
<b>Last Time Shipment Date</b>	30 June ,2023	
<b>Datasheet Attached?</b>	NA	
<b>Qual/Test Data Attached?</b>	NA	
<b>Samples Availability Date:</b>		
<b>Available Alternatives?</b>		
<b>Questions?</b>	<i>Contact your local Amphenol Representative, or Product Manager</i>	
	<i>Jimmy Wang / Product Manager</i>	
	<i>Jimmy.Wang@fci.com</i>	

**Note:**

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .