PHOENIX CONTACT GmbH & Co. KG Flachsmarktstraße 8 32825 Blomberg, Germany Telefon: ++49 / (0) 52 35/300 Telefax: ++49 / (0) 52 35/34 12 00 Internet: http://www.phoenixcontact.com USt-Id-Nr.: DE124613250 WEEE-Reg.-Nr.: DE50738265

PHOENIX CONTACT GmbH & Co. KG · 32823 Blomberg Customer no. (column F)

Company (column G) (column H) (Column I) Dept. Purchase/Materials Management Street (column J) Postcode (column K) Place (column L)

> 01.04.18 Product Marketing

Discontinuation of a product Please forward this information to your electrical engineering departments and/or customers

Dear Sir or Madam

It is always our ambition to offer you state-of-the-art and up-to-date products for your application. For this reason, it is necessary for economical or technical reasons to regularly check our product portfolio and to adjust it according to the product life cycle.

We herewith discontinue the articles in the attached list at the 1st of April 2018. WE discontinue turned contacts of series RC and SM. These contacts can be substituted directly. All crimping tools can still be used for the substitute articles, but please pay attention to the crimp settings, as they may vary. This discontinuation also affects connectors, which are delivered with crimp contacts. These articles can also be found in the enclosed article list.

The replacement PN is the exact same part but with a wider crimp wire range certification.

In order to cover your foreseeable demand of replacement parts, you will still be able to order the mentioned products until 01.04.19 (Last Order). The last shipment will be by 30.04.2019 at the latest (Last Shipment).

We thank you for your understanding and look forward to continue our good cooperation.

Kind regards

PHOENIX CONTACT Connector Technology GmbH

Attachment for the discontinuation of 1st of April, 2018

Article list:

Articles which will be discontinued from our product range (please see enclosed article list)

SAP No.	Article number	Description	Substitute	Substitute article number
1605744	SM-36KP002	Kontaktstift, Crimp, 3,6mm	1607057	SM-36KP009 (1-2,5 mm ²)
				SM-36KP003 (4-6 mm ²)
1622975	SM-36KP019	Kontaktstift, Crimp, 3,6mm	1607057	SM-36KP009 (1-2,5 mm ²)
			1605745	SM-36KP003 (4-6 mm ²)
1603492	RC-58P2000	Kontaktstift, Crimp, 1mm	1602996	RC-1KP2000*
1603495	RC-58S2000	Kontaktbuchse, Crimp, 1mm	1602998	RC-1KS2000*
1602992	RC-1BP2000	Kontaktstift, Crimp, 1mm	1602996	RC-1KP2000*
1602994	RC-1BS2000	Kontaktbuchse, Crimp, 1mm	1602998	RC-1KS2000*
1618261	ST-10KP030	Kontaktstift, Crimp, 1mm	1618458	ST-10KP035
1618254	ST-10KS030	Kontaktbuchse, Crimp, 1mm	1618464	ST-10KS035

Connectors (sets, delivered with contacts), which are affected by the discontinuation:

SAP No.	Article number	So far delivered with the following	Substitute	Substitute article number
		contacts	(contacts)	(contacts)
1626735	RC-12P1N8A15TV	RC-1BP2000	1602996	RC-1KP2000*
1616882	RC-12S1N8A80ZS	RC-1BS2000	1602998	RC-1KS2000*
1624912	RC-12S1N8A80ZX	RC-1BS2000	1602998	RC-1KS2000*

* please notice: the crimping tool settings of the replacement contacts differ from the settings of the previous contacts.