

<b>Company</b>	Trenz Electronic GmbH
<b>PCN Number</b>	PCN-20210326
<b>Title</b>	TEC0053-04 TVS Diode
<b>Subject</b>	BOM change
<b>Issue Date</b>	2021-04-08

## 1 Products Affected

---

This change affects TEC0053 of Revision 04: TEC0053-04.

## 2 Changes

---

### 2.1 #1 Change D6: LNBTVS6-221S to LNBTVS4-222S

---

**Type:** BOM change

**Reason:** Former diodes are Obsolete.

**Impact:** None.

## 3 Method of Identification

---

Boards with Serial number greater than 673885 (white QR Sticker) will have the new Diodes installed.

## 4 Production Shipment Schedule

---

Boards and assemblies produced after August 2021 have the replaced parts installed.

## 5 Contact Information

---

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- [forum.trenz-electronic.de](http://forum.trenz-electronic.de)<sup>1</sup>
- [wiki.trenz-electronic.de](http://wiki.trenz-electronic.de)<sup>2</sup>

---

<sup>1</sup> <http://forum.trenz-electronic.de/>

<sup>2</sup> <http://wiki.trenz-electronic.de/>

- [support@trenz-electronic.de](mailto:support@trenz-electronic.de)<sup>3</sup> (subject = PCN-20210326)
- phone
  - national calls: 05741 3200-0
  - international calls: 0049 5741 3200-0

## 6 Disclaimer

---

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.

---

<sup>3</sup> <mailto:support@trenz-electronic.de?subject=PCN-20210326>