

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Change in the visual appearance of product marking affecting products in packages PG-SSO-4-1, PG-SSO-2-33 and PG-SSO 3-2.

INFORMATION NOTE



N° 085/17

PL=42

Change in the visual appearance of product marking affecting products in packages PG-SSO-4-1, PG-SSO-2-33 and PG-SSO 3-2.

► Products affected:	Sales Name	SP N°	OPN	Package
	Please refer to 1_cip17085 attached.			

► Detailed Change Information:


Subject: Change in the visual appearance of product marking affecting products in packages PG-SSO-4-1, PG-SSO-2-33 and PG-SSO 3-2.

Reason: Laser upgrade release due to obsolete laser system.

Description:


Old

An example for laser marking with existing laser system:



New

An example for laser marking with new laser system:



► Product Identification: Traceability is ensured by different lot number.

► Impact of Change: No change in form, fit or function.

► Attachments: 1_cip17085: affected product list

► Intended start of delivery: From September 2017 onwards.

If you have any questions, please do not hesitate to contact your local Sales office.

INF N°085/17

Change in the visual appearance of product marking affecting



Sales Name	SP number	OPN	Package
TLE4905L	SP000016544	TLE4905LHALA1	PG-SSO-3-2
TLE4905L E6433	SP000016545	TLE4905LE6433HAXA1	PG-SSO-3-2
TLE4906L	SP000012949	TLE4906LHALA1	PG-SSO-3-2
TLE4935L	SP000016376	TLE4935LHALA1	PG-SSO-3-2
TLE4935L E6433	SP000016377	TLE4935LE6433HAXA1	PG-SSO-3-2
TLE4941C E6735	SP000710802	TLE4941CE6735BTMA1	PG-SSO-2-33
TLE4945-2L	SP000013154	TLE49452LHALA1	PG-SSO-3-2
TLE4945-2L E6004	SP001208336	TLE49452LE6004HBXA1	PG-SSO-3-2
TLE4945L	SP000016546	TLE4945LHALA1	PG-SSO-3-2
TLE4946-1L	SP000015003	TLE49461LHALA1	PG-SSO-3-2
TLE4946-2L	SP000398352	TLE49462LHALA1	PG-SSO-3-2
TLE4966L	SP000014135	TLE4966LHALA1	PG-SSO-4-1
TLE4966L E6004	SP000419394	TLE4966LE6004HBXA1	PG-SSO-4-1
TLE4976L	SP000012951	TLE4976LHALA1	PG-SSO-3-2
TLI4906L	SP000604320	TLI4906LHALA1	PG-SSO-3-2
TLI4946-2L	SP000604336	TLI49462LHALA1	PG-SSO-3-2
TLV4906L	SP000604324	TLV4906LHALA1	PG-SSO-3-2
TLV4946-2L	SP000604340	TLV49462LHALA1	PG-SSO-3-2