

<b>PDN Number:</b>	20181218002	<b>PDN Date:</b>	1/21/2019
<b>Title:</b>	Discontinuance of DLP® ECD TRP DMD's		
<b>Customer Contact:</b>	<a href="mailto:DLP-PCN-Team@list.ti.com">DLP-PCN-Team@list.ti.com</a>	<b>Dept:</b>	Quality Services
<b>Last date to order:</b>	6/01/2019	<b>Last date to ship:</b>	12/15/2019
<b>Change Type:</b>	Product Discontinuance - End Of Life		

## Product Discontinuance Notification Details

### Description of Discontinuance:

Texas Instruments Incorporated (TI) is announcing the discontinuance of DLP® ECD TRP devices due to the changing of a proprietary material used in the DMD process. A non-cancelable, non-refundable lifetime buy is being offered as per the Last Date to Order and Last Date to Ship indicated above. The recommended replacement device part numbers are provided in the Product Affected section below. Please contact your local sales representative for availability.

NOTE: There are no samples offered for withdrawn/obsolete products. For samples of any replacement products, please contact your local sales representative.

### Reason for Discontinuance:

The change is part of TI's proactive chemical use policy and continuation of supply

### Product Affected:

Device	Orderable P/N	Replacement Code:	New Orderable P/N	DMD Samples	Sample Order P/N
.5-1080p S410	1910-5232B	Q (requires software update)*	1910-5432B	Jan-2019	X1910-543AB
	1910-5237B	Q (requires software update)*	1910-5437B	Jan-2019	X1910-543AB
	1910-523AB	Q (requires software update)*	1910-543AB	Jan-2019	X1910-543AB
	DLP470NEFXH	Q (requires software update)*	DLP470NEAAFXH	Jan-2019	X1910-543AB
	DLP470NETFXH	Q (requires software update)*	DLP470NETAFXH	Jan-2019	X1910-543AB
.5-4K S410	1910-5332B	Q (requires software update)*	1910-5532B	Jan-2019	X1910-553AB
	1910-5337B	Q (requires software update)*	1910-5537B	Jan-2019	X1910-553AB
	1910-533AB	Q (requires software update)*	1910-553AB	Jan-2019	X1910-553AB
	DLP470TEFXJ	Q (requires software update)*	DLP470TEAAFXJ	Jan-2019	X1910-553AB
.5-WUXGA S410	1912-5032B	Q (requires software update)*	1912-5132B	Jan-2019	X1912-513AB
	1912-5037B	Q (requires software update)*	1912-5137B	Jan-2019	X1912-513AB
	1912-503AB	Q (requires software update)*	1912-513AB	Jan-2019	X1912-513AB
	DLP480REFXG	Q (requires software update)*	DLP480REAAFXG	Jan-2019	X1912-513AB
	DLP480RETFXG	Q (requires software update)*	DLP480RETAFXG	Jan-2019	X1912-513AB
.64WQXGA S610	2516-6032P	Q (requires software update)*	2516-6232P	Jan-2019	X2516-6239P
	2516-6037P	Q (requires software update)*	2516-6237P	Jan-2019	X2516-6239P
	2516-6039P	Q (requires software update)*	2516-6239P	Jan-2019	X2516-6239P
.64WXGA S610	2516-6132P	Q (requires software update)*	2516-6332P	Jan-2019	X2516-6339P
	2516-6137P	Q (requires software update)*	2516-6337P	Jan-2019	X2516-6339P

	2516-6139P	Q (requires software update)*	2516-6339P	Jan-2019	X2516-6339P
.66UHD S610	2715-7032P	Q (requires software update)*	2715-7132P	Jan-2019	X2715-713AP
	2715-7037P	Q (requires software update)*	2715-7137P	Jan-2019	X2715-713AP
	2715-7039P	Q (requires software update)*	2715-7139P	Jan-2019	X2715-713AP
	2715-703AP	Q (requires software update)*	2715-713AP	Jan-2019	X2715-713AP
	DLP660TEFYG	Q (requires software update)*	DLP660TEAAFYG	Jan-2019	X2715-713AP

\*Detailed information can be found on the DLP extranet.

If your controller software comes pre-loaded with the optical engine you purchase, or if your controller software is provided by a third party, please verify the appropriate software version with the provider.

#### Replacement Notes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

#### DMD / Controller / Software Information

DMD	DDP442x	DDP442xHV
	SW / Projects Version	SW / Projects Version
.47 1080p S410 .47 UHD S410 .5 WUXGA S410 .64 WQXGA S610 .64 WXGA S610 .66 UHD S610	Required SW/Projects V9.0 or later	Required SW/Projects v5.1 or later (WQXGA/UHD not supported)

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or contact your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>