

#### 1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PUG Type				
02 005 116 0000001133	See list below	Connectors	KP (Outlet)	
			( • • • • • • • • • • • • • • • • •	

List of part numbers affe	cted			
KP01.1012.01	KP01.1013.01	KP01.1052.01	KP01.1052.06	KP01.1053.01

#### 2 Type of change

- Change of approval markings from UR and CSA to the combined cURus on the socket and packaging label according standard update to UL/CSA 60320-1.
- Rating for UL changed from 10A to 15A.
- Width of the metal connections increased.

#### 3 Detailed description of change



## 4 Reason of change

- The change is due to a standard update to UL/CSA 60320-1
- Increase of cross sections to reach nominal current of 15A at UL

Product Change Notification				PCN KP (Outlet)				
owner	creation date	release date	released by	change order no	rev	page	D40 050 040	
huberth	02.02.2021	02.02.2021	muehlema	2021394	В	1 of 2	D10-052-018	



## 5 Release date

The change takes effect in ww15/2021 (Date code 2115 or higher on label) and lasts approx. 6 months depending on the variant and stock.

# 6 Impact of change and recommended action

Form Yes - Socket and label with new cURus approval marking, UL rating 15A

Metal connections changed

Fit No No change for dimension Function No No change in function

Manufacturing No No change for manufacturing site

Label Yes Label new with cURus approval marking

Packaging No No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet KP (Outlet)	

Product Change Notification				PCN KP (Outlet)			
owner	creation date	release date	released by	change order no	rev	page	D40 050 040
huberth	02.02.2021	02.02.2021	muehlema	2021394	В	2 of 2	D10-052-018