

## PRODUCT DISCONTINUATION

### #PD-ICT-MBM9-12

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ICT	BF1	Discontinuation	Notify Distributors and Field	6/5/2012

*Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.*

#### Reason for Discontinuation:

The exposed LEDs are now over molded with a translucent material. This provides better integration of the LEDs into the connector body. The color of the over mold has also changed from green to black.

#### Warranty Information:

N/A

#### Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N


#### Transaction Dates:

Last Buy from Phoenix Contact: 6/5/2012

Last Scheduled Ship from Phoenix Contact: 6/5/2012

## PRODUCT DISCONTINUATION

### #PD-ICT-MBM9-12



*Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

**Contact Info:**

NATE OWENS  
ICT Field Marketing Lead Specialist  
(717)944-1300x3790  
nowens@phoenixcon.com

Thank you,



---

Loreen Katz, Product Marketing Manager

## PRODUCT DISCONTINUATION

### #PD-ICT-MBM9-12

Discontinued Part#	Type Description	Replacement Part#	Type Description
1501304	SAC-3P-M12Y/2XM12FS-3L	1403627	SAC-3P-M12Y/2XM12FS 3L