

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

## **PRODUCT DISCONTINUANCE NOTICE**

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX11201EUB+	MAX11201AEUB+	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX11201EUB+T	MAX11201AEUB+	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX1162BEUB/V+	MAX1162BEUB+	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX1162BEUB/V+T	MAX1162BEUB+T	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX1238EEE/V+T	MAX1238EEE+T	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX1309ECM/V+	MAX1309ECM+	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX1309ECM/V+T	MAX1309ECM+T	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX1441GUP/V+T	N/A	06-Jan-2015	05-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19000BECB+T	N/A	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX19001BECB+T	N/A	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX19998AETP+T	N/A	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX270C/D	MAX270EWP+	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX5489ETE/V+	MAX5489ETE+	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX5489ETE/V+T	N/A	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX5556ESA-T	N/A	06-Jan-2015	05-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5556GSA+	N/A	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX6002EUR/V+	MAX6002EUR+T	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX9064EUK/V+T	MAX9063EBS+TG45	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX9322ECY+	N/A	06-Jan-2015	05-Jan-2017	The part was not released
Discontinuance	MAX9322ECY+T	N/A	06-Jan-2015	05-Jan-2017	The part was not released

PDN #: M000830I

DATE: 06-Jan-2015