



Product Discontinuation Notice WW2200, January 2022


Cross-Connection Discontinuation – ZQV...N (W-series)

-Revised-

Dear Valued Customer,

Weidmuller would like to inform you about a recent product discontinuation. The ZQV cross-connectors of our W-series will be replaced with the ZQV cross-connectors from our A-series. This decision was made to avoid handling mix-ups with the same-colored (Yellow) cross-connectors from our Z-series and to simplify product variety.

Availability: This change is effective immediately. Affected items are listed below



Exception: ZQV...N 1.5 cross-connectors for the W-series terminals WDU1.5 & WDK1.5 will not be replaced at this point and remain unchanged.

Reason for Change: This product discontinuation has been made to support our continued commitment for improvement and ongoing product development.

Affected article / follow-up:

ZQV 2.5N

1693800000 - ZQV 2.5N/2 GE → 1527540000 - ZQV 2.5N/2
1693810000 - ZQV 2.5N/3 GE → 1527570000 - ZQV 2.5N/3
1693820000 - ZQV 2.5N/4 GE → 1527590000 - ZQV 2.5N/4
1693830000 - ZQV 2.5N/5 GE → 1527620000 - ZQV 2.5N/5
1693840000 - ZQV 2.5N/6 GE → 1527630000 - ZQV 2.5N/6
1693850000 - ZQV 2.5N/7 GE → 1527640000 - ZQV 2.5N/7
1693860000 - ZQV 2.5N/8 GE → 1527670000 - ZQV 2.5N/8
1693870000 - ZQV 2.5N/9 GE → 1527680000 - ZQV 2.5N/9
1693880000 - ZQV 2.5N/10 GE → 1527690000 - ZQV 2.5N/10
1909000000 - ZQV 2.5N/20 GE → 1527720000 - ZQV 2.5N/20
1693890000 - ZQV 2.5N/50 GE → 1527730000 - ZQV 2.5N/50

1717990000 - ZQV 2.5N/2 BL → 1527740000 - ZQV 2.5N/2 BL
1718000000 - ZQV 2.5N/3 BL → 1527770000 - ZQV 2.5N/3 BL
1718010000 - ZQV 2.5N/4 BL → 1527780000 - ZQV 2.5N/4 BL
1718020000 - ZQV 2.5N/5 BL → 1527790000 - ZQV 2.5N/5 BL
1718030000 - ZQV 2.5N/6 BL → 1527820000 - ZQV 2.5N/6 BL
1718040000 - ZQV 2.5N/7 BL → 1527830000 - ZQV 2.5N/7 BL
1718050000 - ZQV 2.5N/8 BL → 1527840000 - ZQV 2.5N/8 BL
1718060000 - ZQV 2.5N/9 BL → 1527870000 - ZQV 2.5N/9 BL
1718070000 - ZQV 2.5N/10 BL → 1527880000 - ZQV 2.5N/10 BL
1909140000 - ZQV 2.5N/20 BL → 1527890000 - ZQV 2.5N/20 BL
1718180000 - ZQV 2.5N/50 BL → 1527920000 - ZQV 2.5N/50 BL

1718080000 - ZQV 2.5N/2 SW → 2831670000* - ZQV 2.5N/2 BK
1718090000 - ZQV 2.5N/3 SW → 2831680000* - ZQV 2.5N/3 BK
1718100000 - ZQV 2.5N/4 SW → 2831690000* - ZQV 2.5N/4 BK
1718110000 - ZQV 2.5N/5 SW → 2831700000* - ZQV 2.5N/5 BK
1718120000 - ZQV 2.5N/6 SW → 2831710000* - ZQV 2.5N/6 BK
1718130000 - ZQV 2.5N/7 SW → 2831720000* - ZQV 2.5N/7 BK
1718140000 - ZQV 2.5N/8 SW → 2831730000* - ZQV 2.5N/8 BK
1718150000 - ZQV 2.5N/9 SW → 2831740000* - ZQV 2.5N/9 BK
1718160000 - ZQV 2.5N/10 SW → 2831750000* - ZQV 2.5N/10 BK
1909130000 - ZQV 2.5N/20 SW → 2831760000* - ZQV 2.5N/20 BK
1718190000 - ZQV 2.5N/50 SW → 2831770000* - ZQV 2.5N/50 BK

ZQV 4N

1758250000 - ZQV 4N/2 GE → 1527930000 - ZQV 4N/2
1762630000 - ZQV 4N/3 GE → 1527940000 - ZQV 4N/3
1762620000 - ZQV 4N/4 GE → 1527970000 - ZQV 4N/4
1758260000 - ZQV 4N/10 GE → 1528090000 - ZQV 4N/10
1909020000 - ZQV 4N/20 GE → **
1758270000 - ZQV 4N/41 → **
1793960000 - ZQV 4N/2 BL → 1528040000 - ZQV 4N/2 BL
1793990000 - ZQV 4N/3 BL → 1528080000 - ZQV 4N/3 BL
1794020000 - ZQV 4N/4 BL → 1528120000 - ZQV 4N/4 BL
1794050000 - ZQV 4N/10 BL → 1528230000 - ZQV 4N/10 BL
1909100000 - ZQV 4N/20 BL → **
1794080000 - ZQV 4N/41 BL → **
1793950000 - ZQV 4N/2 RT → 2480450000 - ZQV 4N/2 RD
1793980000 - ZQV 4N/3 RT → 2480810000 - ZQV 4N/3 RD
1794010000 - ZQV 4N/4 RT → 2480800000 - ZQV 4N/4 RD
1794040000 - ZQV 4N/10 RT → 2480740000 - ZQV 4N/10 RD
1909150000 - ZQV 4N/20 RT → **
1794070000 - ZQV 4N/41 RT → **
1793970000 - ZQV 4N/2 SW → 2810840000* - ZQV 4N/2 BK
1794000000 - ZQV 4N/3 SW → 2810880000* - ZQV 4N/3 BK
1794030000 - ZQV 4N/4 SW → 2810890000* - ZQV 4N/4 BK
1794060000 - ZQV 4N/10 SW → 2810830000* - ZQV 4N/10 BK
1909120000 - ZQV 4N/20 SW → **
1794090000 - ZQV 4N/41 SW → **

1717900000 - ZQV 2.5N/2 RT → 2108470000 - ZQV 2.5N/2 RD
1717910000 - ZQV 2.5N/3 RT → 2108890000 - ZQV 2.5N/3 RD
1717920000 - ZQV 2.5N/4 RT → 2108700000 - ZQV 2.5N/4 RD
1717930000 - ZQV 2.5N/5 RT → 2108710000 - ZQV 2.5N/5 RD
1717940000 - ZQV 2.5N/6 RT → 2108720000 - ZQV 2.5N/6 RD
1717950000 - ZQV 2.5N/7 RT → 2108810000 - ZQV 2.5N/7 RD
1717960000 - ZQV 2.5N/8 RT → 2108870000 - ZQV 2.5N/8 RD
1717970000 - ZQV 2.5N/9 RT → 2108900000 - ZQV 2.5N/9 RD
1717980000 - ZQV 2.5N/10 RT → 2108910000 - ZQV 2.5N/10 RD
1909110000 - ZQV 2.5N/20 RT → 2108920000 - ZQV 2.5N/20 RD
1718170000 - ZQV 2.5N/50 RT → 2109000000 - ZQV 2.5N/50 RD

1193260000 - ZQV 2.5N/2 WS → 2831560000* - ZQV 2.5N/2 WT
1193270000 - ZQV 2.5N/3 WS → 2831570000* - ZQV 2.5N/3 WT
1193280000 - ZQV 2.5N/4 WS → 2831580000* - ZQV 2.5N/4 WT
1193290000 - ZQV 2.5N/5 WS → 2831590000* - ZQV 2.5N/5 WT
1193300000 - ZQV 2.5N/6 WS → 2831600000* - ZQV 2.5N/6 WT
1193310000 - ZQV 2.5N/7 WS → 2831610000* - ZQV 2.5N/7 WT
1193320000 - ZQV 2.5N/8 WS → 2831620000* - ZQV 2.5N/8 WT
1193330000 - ZQV 2.5N/9 WS → 2831630000* - ZQV 2.5N/9 WT
1193340000 - ZQV 2.5N/10 WS → 2831640000* - ZQV 2.5N/10 WT
1193350000 - ZQV 2.5N/20 WS → 2831650000* - ZQV 2.5N/20 WT
1010820000 - ZQV 2.5N/50 WS → 2831660000* - ZQV 2.5N/50 WT

ZQV 6N

1908210000 - ZQV 6N/2 → 1985740000 - ZQV 6N/2
1908220000 - ZQV 6N/3 → 1985760000 - ZQV 6N/3
1908230000 - ZQV 6N/4 → 1985780000 - ZQV 6N/4
1908240000 - ZQV 6N/20 → **

* in creation; articles will be visible in E-shop & online catalog once established

** please reference cross-connectors with smaller/larger pole count


Restrictions when cross-connectors are used with the following terminal blocks:

- ZDL 2.5 → cross-connector cannot be used in combination with SIHA3 fuse holder plug
- ZDUA / ZDUB → cross-connector cannot be used in combination with central marker
- ZT 2.5.../ ZDT 2.5.../ ZTTR 2.5 (WEICOS) → cross-connector cannot be used in combination with cross-connector "...2AN/QV..."
- WDU 4 & WMA 4 → cross-connector cannot be used in combination with WAD 5 marker
- WDU 4N → cross-connector cannot be used in combination with WAD 4

- markers or WTA 1 test adapters
- WDK 4N → terminal connecting point above the cross-connection: ferrules collide with the cross-connection
- P-Series → ZQV...N of the A-series is 5.08 mm higher → not finger-safe

We apologize for any inconvenience this may cause.
If you have any questions, please contact your respective Weidmueller sales representative or Weidmueller's technical support department at 800-849-9343.

Best regards,



Hannah Witopil
Jr. Product Manager - Terminals
Cabinet Products Division



Weidmuller Inc. |, 821 Southlake Blvd. |, Richmond |, Virginia | 23236 |, United States |

[Unsubscribe](#) [Manage preferences](#)