



Subject: End Of Life: Laird 42 material (42Txxx)

Dear Customer,

The above Laird Toroidal material has been made EOL by product management.

The primary reasons for obsoleting this material are due to low demand and very low expectations for this material in the market place.

Laird Product Manager has identified the standard 35 material as a potential alternative to the now EOL 42mat.

Part prints and samples can be provided to you for your evaluation and comparison as needed. Please contact me if you have any questions or need additional information and I will be glad to assist you.

Ed Anderson

Laird PMBU

Account Specialist Distribution

Phone: 636-898-6228

Ed.anderson@lairdtech.com