

## Product Discontinuance Notice - PDN 11\_0015 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

## **PDN Title:**

Obsolescence notification for models AD7819YRU and AD7819YRU-REEL7

Publication Date:27-Jan-2011Last Time Buy Date:27-Jan-2012Last Time Ship Date:27-Jan-2013

## Reason For Discontinuance

Discontinuance is due to decreased activity of these leaded (Pb) bearing models.

## Comments

RoHS compliant replacement models are available to order.

Supporting Documents None

	For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive							
mericas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan:	PDN_Japan@analog.com			
				Rest of Asia:	PDN_ROA@analog.com			

PDN 11_0015 Discontinued Parts Material List							
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments			
AD7819YRU	AD7819	AD7819YRUZ	YES				
AD7819YRU-REEL7	AD7819	AD7819YRUZ-REEL7	YES				

Appendix A - PDN 11_0015 Revision History						
Rev	Publish Date	Rev Description				
Rev	27-Jan-2011	Initial Release				

Analog Devices, Inc. Proprietary Information

Docld:268 Layout Rev.2 Parent Docld:None