

PRODUCT CHANGE NOTIFICATION

Product Category POWER AND CONNECTIVITY 20200610-01

Product Group INTELLIGENT INFRASTRUCTURE

ISSUE DATE: 20200629

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

In an effort to optimize the available portfolio; the intelligent infrastructure team is removing those parts from the marketplace which have little to no demand for the last 2.5 years. As needed; please contact Panduit Tech. for support and for a possible Panduit G5 replacement PDU.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	1	1
Old product discontinuation date*	2020	10	15

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Type
GMSP-A3204RD/N	No Replacement
GMSP-A3204BU/N	No Replacement
GMSP-A3245BU/N	No Replacement
GMSP-A3245RD/N	No Replacement
EX3P32CRCP/NS	No Replacement
PC14C13BU8-Q	No Replacement
GMSP-A3260RD/N	No Replacement
GMSP-A3260BU/N	No Replacement
ZAEI-01-UNI	No Replacement
EXL1530R30P12NS	No Replacement
NETCOM-PH	No Replacement
EX1P32CRCP/NS	No Replacement
EXCRL630P12/NS	No Replacement
ZETHL-14	No Replacement
ZAEI-11-UNI-A	No Replacement
GMSP-A2256BL/N	No Replacement
CRD-02-10PK	No Replacement
GMSP-A3247BU/N	No Replacement
ZARMSC2-01	No Replacement
GMSP-A3247RD/N	No Replacement
ZETHL-15	No Replacement
PC14C13RD4-Q/D	No Replacement
EXCRL2230P12/NS	No Replacement
PCAPPL3/N	No Replacement
PC14C13BU4-Q/D	No Replacement
PC14C13BU6-Q	No Replacement
PC14C13RD6-Q	No Replacement
GMSP-A1851BU/N	No Replacement
GMSP-A1851RD/N	No Replacement
ZEKPKIT-01	No Replacement
IMSNRE1	No Replacement
PVQ-MIQAPCVR	No Replacement
ZAIM-01	No Replacement
ZAEI-01-UNI-A	No Replacement
ZC663-01/N	No Replacement
ZEDL05-02	No Replacement
ZEDL05-01	No Replacement
PC14C13BU2-Q	No Replacement
ZC630	No Replacement
ZC644-01	No Replacement
PC20C13BU6-Q	No Replacement
ZEDL06	No Replacement
PC20C19BU1.5M-Q	No Replacement
PC20C19RD1.5M-Q	No Replacement
ISSHWMAINT	No Replacement
ZC705A	No Replacement
DHSCSH-08/N	No Replacement
GMSP-A1697BU/N-KIT	No Replacement
GMSP-A1697RD/N-KIT	No Replacement
GMSP-A3251BU/N	No Replacement
GMSP-A3251RD/N	No Replacement
GMSP-A2252WH/N	No Replacement
GMSP-A2256BU/N	No Replacement
GMSP-A2256RD/N	No Replacement
NS32-5604-3P-WE-PC	No Replacement
PC14C13BU4-Q	No Replacement
PC14C13RD2-Q	No Replacement

PC14C13RD4-Q No Replacement
PC14C13RD10-Q No Replacement
PC14C13YL2-Q No Replacement
PC14C13YL4-Q No Replacement
PC14C13YL8-Q No Replacement
PC14C13YL10-Q No Replacement
PC20C19BU10-Q No Replacement
PC20C19RD6-Q No Replacement
PC20C19RD10-Q No Replacement
PC20C19YL1.0M-Q No Replacement
PC20C19YL2-Q No Replacement
PC20C19YL2.0M-Q No Replacement
PC20C19YL4-Q No Replacement
PC20C19YL6-Q No Replacement
PC20C19YL8-Q No Replacement
PC20C19YL10-Q No Replacement
RZC700G No Replacement
ZAEI-01-BP No Replacement
ZAEI-11-BP-A No Replacement
ZC631 No Replacement
ZC632R No Replacement
ZC639 No Replacement
ZC644-01/N No Replacement
ZC663-01 No Replacement
ZC700D No Replacement
ZC705B No Replacement
ZC706A No Replacement
ZC633R No Replacement