


Product Change Notification (PCN)

PCN Number 505916 Date Issued February 21, 2019 Reason for Change Change to Product Change Type Description This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences. Reason for Short Notice **Corrective Actions** Assessment of Change First article inspection Internal Molex Qualification Date September 17, 2018 Sample Availability Date September 17, 2018 (Changed Part) Planned Implementation Date March 16, 2019 Method of Identifying Change

Lot information on label

Before Change

■ LPH Receptacle - 45984 Series



After Change

Overview

- Plastic is being added in the inner signal cores to better support the terminals.
- Product Impact
 - No impact to fit, form or function.
 - The inner row of terminals were found to be influenced by handling and caused the contact gap to be impacted after the assembly process. Extra plastic was added to the outer row of terminals for better support and reduce the amount of movement.
- Part Number Impact All of series 45984
 - See attached impacted parts list
- Samples available upon request
 - Qualification Reports and samples available upon request after the date shown

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:505916" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part #