



SIERRA WIRELESS PRODUCT CHANGE NOTICE

OVERVIEW

DATE ISSUED:	Oct 21 st , 2022	TRACKING NUMBER:	4134961
ISSUED BY:	IoT Solutions Product Management		
PRODUCTS AFFECTED:	RC7611		
SKUS AFFECTED:	1105020, 1105021		
BULLETIN:	Change of Primary Factory		
URGENCY:	Normal		
FOR DISTRIBUTION TO:	Customers using products affected and their partners		

Summary

As part of ongoing risk mitigation and production planning, Sierra Wireless is changing the primary production factory for the affected to SKU to one located in Mexico. Production at our Vietnam factory will remain an available option as well.

Change Details

There are no changes to the products' design, quality, specifications, form, fit or function. Sierra Wireless uses the same production process, test equipment, material, and control plan in all factories. Manufacturing at the Mexico factory does not affect the hardware or RF performance and will not impact most regulatory and carrier certifications. Some country regulatory may need to be updated to append the additional country of origin.

Units manufactured in the Mexico factory will display “Made in Mexico” or “Made in MEX” on the module, reel, and box labels.

There is no change to product SKU numbers, existing SKU numbers will be used for units manufactured at both sites.

Timeline

Shipments for the affected SKU are expected to transition to the Mexico factory in late February or March 2023.

More information

For more information, please contact your Sierra Wireless Sales or Customer Quality representative.