

PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PTD 20211206-2

Product Group ID AND SAFETY

ISSUE DATE: 6-Dec-21

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Due to the upcoming launch of VeriSafe 2.0, Panduit will be discontinuing the VeriSafe 1.0 Hazardous Locations AVTs. The next generation VeriSafe 2.0 will be a direct replacement and have all of the same hazardous locations ratings as the SKUs being discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	4	18
Old product discontinuation date*	2022	5	1

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
VS-AVT2-C02L03	Direct	VS2-AVT-3PB-02
VS-AVT2-C08L10	Direct	VS2-AVT-3PB-08