



Expertise Applied | Answers Delivered

Littelfuse, Inc.
8755 West Higgins Road, Suite 500
Chicago, IL 60631 USA
(773) 628-1000

May 16th, 2019

RE: Littelfuse Obsolescence Notification

Dear Valued Customer,

Littelfuse, Inc., while committing to supporting you through a robust supply chain, regrets to notify you that due to an unforeseen circumstance with a supply chain partner, part number 98635-01 is being made obsolete.

We have recently been notified that a legacy molding vendor no longer has the means to support production of such a product. As this is a very mature product that has seen sharply declining volumes in recent years, Littelfuse is not able to support additional means of production for this product.

Limited quantities of this part are currently in stock and available for purchase, as supplies last. Unfortunately, Littelfuse is unable to offer alternative products as effective replacements for this part. Please contact your local Littelfuse representative with any additional questions.

Thank you for your continued support,

A handwritten signature in black ink that reads 'Zacke Naughton'.

Zacke Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products