

March 2022

### Important Customer Information: Change of Globtop Material HYT 939 sensors

Dear Customers and Business Partners,

**HYT 939 Digital Temperature and Humidity sensor product** made by our company has been upgraded to provide better availability initiated by an unexpected termination of standard Globtop material supply.

Technically and functionally, the replacement Globtop and its according sensor replacement products have undergone extensive qualification tests over the past 18 months. The new replacement sensors have passed all the tests and have **no known differences** in regards of the application, sensors characteristics and functionality. The new versions are fully exchangeable with the former products. For a detailed description please refer to the provided **ECN\_A22.024**.

We encourage you to update your product now with the new part numbers and please do not hesitate to contact us for **free approval samples**.

Due to lack of supply of the current Globtop there are **very limited last possible deliveries of the current sensors**. Any **blanket orders** must be revised or switched to the corresponding alternatives immediately. Unfortunately, and with immediate effect, we can't accept any further orders for the discontinued sensors however **we accept orders of the new replacement sensors**.

You received this message because you have purchased effected sensor products within the last two years.

If you have any questions, please do not hesitate to contact us, thank you very much.

Best regards,

*Alan Ravizza*

Alan Ravizza  
Managing Director USA Division