

# PRODUCT DISCONTINUATION

**PD\_064\_06    !! UPDATE !!**

Reason:                    Portfolio optimization

Original:                  Product Discontinuation PD\_064\_06 dated 03. July 2006

**Update:                    [BBY 53-03LRH E6817: Discontinuation revoked](#)**

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
BAR 95-02LS E6327	SP000099220	PIN Diode	TSSLP-2-1	no replacement			
BBY 53-03LRH E6327	SP000083405	VCO Diode	TSLP-3-7				
<del>BBY 53-03LRH E6817</del> <b>Discont. revoked</b>	SP000014957	VCO Diode	TSLP-3-7				
BF 543 E7810	SP000010964	RF-MOSFET	SOT23				

Last order:	01. December 2006
Last delivery:	01. June 2007