

**Issue Date:** October 20<sup>th</sup>, 2020

Dear Valued Customer,

This notice is to inform you of the obsolescence of items that you have purchased from Littelfuse.

***Description of the Change:***

- We will obsolete and no longer support production of 40102.

***Reason for The Change:***

- Littelfuse was recently notified that one of our suppliers is no longer able to manufacture a component necessary to continue production of this finished good.
- This finished good is very mature and has seen sharply declining volumes in recent years. As such, the investments required to re-tool and re-source the critical component are not supported by current and projected demand.

***Effective Date of the Change:***

- Due to the sudden nature of this interruption, this obsolescence is effective immediately.


***What You Need to Do:***

- We will do our best to fulfill existing orders in the order in which they were received with the remaining componentry stock available. We will not be able to support any additional orders or last time buys.
- Any future demand for these parts should be shifted to alternative, similar products. We will assist on identifying suggested replacements on a customer-by-customer, application-by-application basis, so please contact us with questions.

For any questions, please reach out to either your local Customer Service or Inside Sales Representative.

We appreciate your continued partnership and business.

Sincerely,



Zachary Naughton  
Global Product Manager  
Littelfuse Commercial Vehicle Products