

+ CORPORATE HEADQUARTERS

707 Dayton Road
PO Box 1040
Ottawa, IL 61350
USA

p: (800) 346-3119
f: (815) 433-5109

+ EUROPEAN HEADQUARTERS

Westlink Commercial Park
Unit 10
Oranmore, Co. Galway
Ireland

p: + 353 91 792444
f: + 353 91 792445

+ CELLULAR PRODUCTS GROUP

Sokolská 71
562 04 Ústí nad Orlicí III.
Czech Republic

p: +420 465 521 020
f: +420 464 647 299

Product EOL Notice

June 29, 2018

Model	Description
BB-854-11700	GIGA-MINIMC/LFPT MOD, TX/SFP (REQ1 IE-SFP/1250)
BB-854-11701	Giga-MiniMc/LFPT Module, TX/SX-MM850-SC
BB-856-11700	Giga-MiniMc with LFPT - SFP
BB-856-11701	Giga-MiniMc with LFPT - MM850SC
BB-856-11702	Giga-MinMc/LFPT, TX/LX-MM1300-SC
BB-856-11703	Giga-MiniMc with LFPT - SM1310SC
BB-856-11704	Giga-MinMc/LFPT, TX/LX-SM1310/PLUS-SC
BB-856-11710	Giga-MinMc/LFPT, TX/SSLX-SM1310
BB-856-11711	Giga-MinMc/LFPT, TX/SSLX-SM-SC (1550xmt/1310rcv)
BB-856-11714	Giga-MinMc/LFPT, TX/SSLX-SM-SC (1310xmt/1550rcv)
BB-856-10728	Giga-MiniMc, TX/LX-MM1300 -SC (W/AC ADAPTER)
BB-856-10736	Giga-MiniMc, TX/SSLX-SM-SC 1310T/1550R+AC ADPTR
BB-856-10737	Giga-MiniMc, TX/SSLX-SM-SC 1550T/1310R+AC ADPTR
BB-854-10720	MiniMc-Gigabit Module, TX/SX-MM850-SC
BB-854-10721	MiniMc-Gigabit Module, TX/LX-SM1310-SC
BB-854-10728	Giga-MiniMc Module, TX/LX- MM1300-SC
BB-854-10730	Giga-MiniMc Module, TX/SX- MM850-SC
BB-854-10731	Giga-MiniMc Module, TX/LX- SM1310-SC
BB-854-10734	Giga-MiniMc Module, TX/SSLX -SM-SC (1310T/1550R)
BB-855-10732	MINIMC-GIGABIT, TX/LX-SM1310 /PLUS-SC(W/AC ADPTR)
BB-855-10734	MINIMC-GIGABIT, TX/SSLX-SM 1310-SC(W/AC ADAPTER)
BB-855-10735	MINIMC-GIGABIT, TX/SSLX-SM 1550-SC(W/AC ADAPTER)
BB-855-10736	MINIMC-GIGABIT, TX/SSLX-SM1310/PLUS-SC W/AC ADPTR
BB-855-10737	MINIMC-GIGABIT, TX/SSLX-SM1550/PLUS-SC W/AC ADPTR

This is the end-of-life announcement for the products listed above. Last time buy orders will be accepted until September 30 2018.

Product Migration Path:

Current	Replacement
BB-854-11700	BB-856-10747
BB-854-11701	BB-856-10730
BB-856-11700	BB-856-10747
BB-856-11701	BB-856-10730
BB-856-11702	No replacement
BB-856-11703	BB-856-10731
BB-856-11704	BB-856-10732
BB-856-11710	No replacement
BB-856-11711	BB-856-10734
BB-856-11714	BB-856-10735

+ CORPORATE HEADQUARTERS

707 Dayton Road
PO Box 1040
Ottawa, IL 61350
USA

p: (800) 346-3119
f: (815) 433-5109

+ EUROPEAN HEADQUARTERS

Westlink Commercial Park
Unit 10
Oranmore, Co. Galway
Ireland

p: + 353 91 792444
f: + 353 91 792445

BB-856-10728	BB-856-10730
BB-856-10736	BB-856-10747, BB-808-38221
BB-856-10737	BB-856-10747, BB-808-38222
BB-854-10720	BB-856-10730
BB-854-10721	BB-856-10731
BB-854-10728	No replacement
BB-854-10730	BB-856-10730
BB-854-10731	BB-856-10731
BB-854-10734	BB-856-10747, BB-808-38221
BB-855-10732	BB-856-10747, BB-808-38203
BB-855-10734	BB-856-10747, BB-808-38221
BB-855-10735	BB-856-10747, BB-808-38222
BB-855-10736	BB-856-10747, BB-808-38223
BB-855-10737	BB-856-10747, BB-808-38224

+ CELLULAR PRODUCTS GROUP

Sokolská 71
562 04 Ústí nad Orlicí III.
Czech Republic

p: +420 465 521 020
f: +420 464 647 299

Contact B+B SmartWorx for availability. Full product documentation is available on our website www.advantech-bb.com, or via our support staff: support@advantech-bb.com

Thank You,



Stan Simmons | Product Sales Manager