



TE Connectivity

Product Change Notification: E-19-008351-C

PCN Date: 15-JUL-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
SR6 6 pole Force Guided Relay

Description of Changes
TE Connectivity's (TE) SR6 6 pole Force Guided Relay have a China Compulsory Certificate (CCC) mark of product certification. The Chinese Certification and Accreditation Authority (CNCA) has published new Implementation Rules for Compulsory Certification requiring reapproval by CCC. TE has been informed by CCC that as of May 8th, 2019 the certificate has been suspended. TE is expected to regain the CCC approval during the week of July 15 - 19, 2019. Until the product is recertified, TE will remove the CCC marking from the Force Guided Relay products SR6 effective with May 27, 2019. TE will notify our customers when we can apply the CCC mark to our Force Guided Relay products again which is expected in the week of July 15 - 19, 2019.

Reason for Cancellation:
PCN has been distributed. Customers were informed about the missing approval. Approval has been reobtained in the mean time. Customers must be informed About the recertification of the relays. Therefore, a new ECR and new PCN must be initiated and this one can be canceled.

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415353-1	NO			"SR6M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
6-1415027-1	NO			"SR6D4024"			
6-1415537-5	NO			"SR6A6K24"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"V23050-A1024-A533", "V23050A1024A533"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415353-1	NO			"SR6M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
6-1415027-1	NO			"SR6D4024"			
6-1415537-5	NO			"SR6A6K24"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415353-1	NO			"SR6M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
6-1415027-1	NO			"SR6D4024"			
6-1415537-5	NO			"SR6A6K24"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			