

Product Change Notification (PCN)

PCN Number 502156 Date Issued February 13, 2017

Reason for Change

Change to Product

Change Type Description

This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.

Reason for Short Notice

Corrective Actions

Assessment of Change

Test report/Specification Test Report

Internal Molex Qualification Date

March 20, 2017

Sample Availability Date (Changed Part)

March 20, 2017

Planned Implementation Date


August 15, 2017

Method of Identifying Change

Date code

Before Change

 Hooks and pockets being added at the 4 corners of the SFP 2x1 Connector Assemblies will keep the EMI finger straps tight to the cage body



tial Information All Rights Reserved, Unauthorized Reproduction/Distribution is Prohibited.



After Change

Overview

- Hooks and pockets being added at the 4 corners of the SFP 2x1 Connector Assemblies will keep the EMI finger straps tight to the cage body.
- This will prevent spring finger damage during the insertion through the customer's bezel opening.
- Product Impact
 - There will be no impact to the product form, fit or function
- Part Number Impact
 - Impacts 76044 series connectors
- PPAP and samples available upon request

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:502156" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part # 760445001