

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with columns for Depression of Wet Bulb (21-32°F) and DRY BULB READINGS -- FAHRENHEIT (34-120). Includes instructions for use.

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with columns for Depression of Wet Bulb (1-20°F) and DRY BULB READINGS -- FAHRENHEIT (34-120).

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with columns for Depression of Wet Bulb (10.5-20°C) and DRY BULB READINGS -- CELSIUS (-5 to 50). Includes instructions for use.

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with columns for Depression of Wet Bulb (0.5-10°C) and DRY BULB READINGS -- CELSIUS (-5 to 50).