

Product Discontinuation Notice

March 25, 2013

Discontinuation of AHK (HK) Relays



1. Reason: Replacement part

2. Affected parts: All types

HK (AHK) relays		
	All types	АНКООООО

3. Last time buy: End of September 2013

4. Substitution:

Affected part number	Replacement Product	Replacement part number
AHKOOOOO	HL relays	HLO-OOO-ACOOOV-F HLO-OOO-DCOOOV-F

Any questions, please contact your local Panasonic Sales representatives.

(Ref#: T-1289-21)