



**TO:** DIGI-KEY CORPORATION  
4206 33RD ST NORTH FARGO ND United States

**Subject:** ADP5090 Product Deviation Advisory

**Date:** 17-May-2022

## **I. Material Identification Table(s)**

**Advisory:** Notification of previously released Non-Conforming material. See Section III. action table.

<b>ADI Model</b>	<b>ADI Product</b>	<b>Lot ID</b>	<b>Date Code</b>	<b>Quantity</b>	<b>Sales Order #</b>	<b>DN #</b>
ADP5090ACPZ-2-R7	ADP5090	4291845.1	1824	1500	57307784	8002714237
ADP5090ACPZ-2-R7	ADP5090	4526242.1	1844	1500	57530731	8004313329

## **II. Description of Non-Conformance**

### Description of Non-Conformance

ADP5090ACPZ-2-R7 was incorrectly branded with 'LPN' on the marking. The correct branding is 'LT3'.

### Risk Assessment

The issue is only with the branding. All of the affected material was fabricated, assembled, and tested against released processes and specifications.

### Impact to Delivery

There is no Finished Goods material in warehouse for replacement at this moment. Please check local Analog Devices sales office about the lead time for orders.

### III Actions Required for Previously Released Non-Conforming Material

#### Actions Required for Previously Released Non-Conforming Material



No Action Required

Analog Devices is committed to providing any additional information necessary to satisfy customer product concerns and to ensure continuity of supply. Please contact your regional Customer Quality Engineer for any additional questions or concerns:

AMERICAS: Bill Gaffney 781-937-2745  
EUROPE: Stefan Hacker +49-89-76903-303  
JAPAN: Masao Shimizu +81-3-5402-8646  
SOUTH EAST ASIA: Gary Hua +86 0312-320-8031

bill.gaffney@analog.com  
stefan.hacker@analog.com  
masao.shimizu@analog.com  
gary.hua@analog.com



**TO:** DIGI-KEY CORPORATION  
701 BROOKS AVE SOUTH THIEF RIVER FALLS MN United States

**Subject:** ADP5090 Product Deviation Advisory

**Date:** 17-May-2022

## **I. Material Identification Table(s)**

**Advisory:** Notification of previously released Non-Conforming material. See Section III. action table.

<b>ADI Model</b>	<b>ADI Product</b>	<b>Lot ID</b>	<b>Date Code</b>	<b>Quantity</b>	<b>Sales Order #</b>	<b>DN #</b>
ADP5090ACPZ-2-R7	ADP5090	3474505.1	1511	1500	8992563	19178015

## **II. Description of Non-Conformance**

<b>Description of Non-Conformance</b>
ADP5090ACPZ-2-R7 was incorrectly branded with 'LPN' on the marking. The correct branding is 'LT3'.
<b>Risk Assessment</b>
The issue is only with the branding. All of the affected material was fabricated, assembled, and tested against released processes and specifications.
<b>Impact to Delivery</b>
There is no Finished Goods material in warehouse for replacement at this moment. Please check local Analog Devices sales office about the lead time for orders.

### III Actions Required for Previously Released Non-Conforming Material

#### Actions Required for Previously Released Non-Conforming Material



No Action Required

Analog Devices is committed to providing any additional information necessary to satisfy customer product concerns and to ensure continuity of supply. Please contact your regional Customer Quality Engineer for any additional questions or concerns:

AMERICAS: Bill Gaffney 781-937-2745  
EUROPE: Stefan Hacker +49-89-76903-303  
JAPAN: Masao Shimizu +81-3-5402-8646  
SOUTH EAST ASIA: Gary Hua +86 0312-320-8031

bill.gaffney@analog.com  
stefan.hacker@analog.com  
masao.shimizu@analog.com  
gary.hua@analog.com