

Global Change Notification (GCN)

Product Family External MiniSAS cable assem 10619145


GCN Number

Series 74547 December 24, 2013

Date Issued

Reason For Change Product Component Change

Change Description The purpose of this letter is to inform you that change of the core thickness between top layer/inner 2 layer and inner 3 layer and bottom layer from 8mil to 9mil while the total thickness for the PCB doesn't change will be implemented on 745470044 . The affected FG please refer to Worksheet. This letter takes the place of notice customer the reason of change is impedance performance improved . We verify Impact of the change is confirmed as Quality improvement .



Datecode on the PCB

Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception Not Applicable

Assessment Of Change (How Product Will Be Qualified & Validated) the enhancement of the PCB component design without changing the entire overall dimensional thickness" and we don't hv any nonconformance of PCB

Internal Molex Qualification Date (Planned Date Information Available) May 15, 2013

Sample Availability Date (Changed Part) June 15, 2014

Date of Implementation June 15, 2014

Method of Identifying Change Date code as below picture

Recommended Replacement Parts NA

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com