



Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN20015

11/6/2020

CLASSIFICATION OF CHANGE:

The marking color has been updated for the TCP70 fuses.

DESCRIPTION OF CHANGE:

The TCP70 fuses will use black ink on the body for their markings.

REASON FOR CHANGE:

The harmonization of color marking.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PART NUMBERS AFFECTED

BK1-TCP70-5-R

BK1-TCP70-6-R

BK1-TCP70-15-R

BK1-TCP70-30-R

BK1-TCP70-40-R

TIME SCHEDULE:

Effective immediately

ISSUED BY:

Jenan Krouchick

Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html/>