



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-140910

PCN Date: 31-MAY-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

CLUSTER BLOCK TERMINAL .090 DIA.

Description of Changes

Packaging Reel Improvement. -Hole on the Reel core to fix the Terminal

Fixed of Fiber TAPE

Fixed of core Hole

Reel part	Reel status		Fixed method	Different	Reel part	Reel status		Fixed method	Different
995225-1				1. No hole 2. Fixed of FIBER TAPE	2400473-1				1. Hole on the core 2. Fixed of core hole

Other attachments:

[Reel Change](#)

Reason for Changes:

PCN Attributes:

Product Category:

Packaging

Kind of Change:

Packaging Type

Change Feature:	Potential Customer Impact:
Reel	No Customer Impact
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	30-JUN-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1599105-1	NO						
2825313-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1599105-1	NO						
2825313-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1599105-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2825313-1	NO						

Part Number(s) being Modified:




Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1599105-1	NO						
2825313-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1599105-1	NO						
2825313-1	NO						

Paper reel appearance status 999225-1 & 2400473-1




Before

Reel part	Reel status	Fixed method	Different
995225-1	 		<ol style="list-style-type: none"> 1. No hole 2. Fixed of FIBER TAPE

Note:

1. Paper core status is different
2. Fixed method is different
3. Flag have small change , Two side the circular hole change to the rectangle hole

After

Reel part	Reel status	Fixed method	Different
2400473-1	 		<ol style="list-style-type: none"> 1. Hole on the core 2. Fixed of core hole

