



## Customer Information Notification

201609015I

**Issue Date:** 12-Sep-2016

**Effective Date:** 31-Oct-2016

Dear

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online



# QUALITY

### Change Category

- |  |   |  |   |  |
|--|---|--|---|--|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process   | <input type="checkbox"/> Product Marking           | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                                    |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification  | <input type="checkbox"/> Test Process   | <input type="checkbox"/> Errata                                    |
| <input type="checkbox"/> Wafer Fab Location  | <input type="checkbox"/> Assembly Location  | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input checked="" type="checkbox"/> Electrical spec./Test coverage |

## Correction of Qrr and Trr on Datasheets

### Information Notification

NXP are correcting the Qrr and Trr values in the data

#### Qrr

BUK9Y22-100E / PSMN021-100YL was 66 now 52  
 BUK9Y19-100E / PSMN019-100YL was 67.7 now 56  
 BUK9Y15-100E / PSMN015-100YL was 64 now 79  
 BUK9Y12-100E / PSMN012-100YL was 65 now 90

#### Trr

BUK9Y22-100E / PSMN021-100YL was 38.2 now 37  
 BUK9Y19-100E / PSMN019-100YL was 38.7 now 38  
 BUK9Y15-100E / PSMN015-100YL was 38 now 44  
 BUK9Y12-100E / PSMN012-100YL was 39 now 47

#### Why do we issue this Information Notification

This was incorrectly specified at original release

#### Identification of Affected Products

Product identification does not change

### Impact

no impact to the product's functionality anticipated.

#### Data Sheet Revision

A new datasheet will be issued

**Disposition of Old Products**

N/A

**Remarks**

Draft datasheets attached

**Contact and Support**

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

**e-mail address**      powermos.pcn@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

**About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[View Notification](#)

[Subscription](#)

[Support](#)

[NXP | Privacy Policy | Terms of Use](#)

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.

**Affected Part Numbers**

BUK9Y19-100E,115

BUK9Y19-100E,115

BUK9Y12-100E,115

BUK9Y22-100E,115

BUK9Y15-100E,115

BUK9Y22-100E,115

BUK9Y12-100E,115