

Product Change Notice

Classification of change:	Change of components
Description of change:	Components replaced and optimized
Reason for change:	Compliance with SA8000 certification (conflict minerals); manufacturing and supply chain optimization
Expected influence on quality, reliability, and performance:	There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.
Products affected:	<ul style="list-style-type: none">• Arduino Due (A000062)
Time schedule:	Start shipment date: Dec 15th, 2021 Last time buy date: n/a Last time shipment date: n/a
Sample availability:	n/a
Qualification data:	n/a
Issued by:	Head of Makers Business Unit: Alessandro Ranellucci
Contact information:	For questions or comments, please contact your Arduino sales representative.

Notice

As part of the ongoing effort to adopt the SA8000 certification regarding conflict minerals and optimize our supply chain and manufacturing processes we applied the following changes to the circuit:

- Removed tantalum capacitors
- Replaced the micro USB connector with the same part number used on other Arduino boards
- Changed some resistor values to simplify the BoM

None of such changes affect form, fit and function of the product or has any other noticeable effects for users on software compatibility, behavior or electrical specifications.