

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY **20180827-1**

ISSUE DATE: 27-Aug-18

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

25-pair cable patch cord assemblies of the type "UTPCH*25Y" were incorrectly indicated to be listed to UL1863 but in fact were not. There is no change to the cable assemblies themselves other than references to them being listed to UL1863 have been removed. The cable used continues to meet UL444 (ETL Verified) and UL1666, and the RJ45 plugs continue to be listed to UL1863.

Example Photos of 25-pair cable patch cord assemblies



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2018	8	27
Old product discontinuation date*			

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)
UTPCH1012PP25Y
UTPCH10L25Y
UTPCH10LR25Y
UTPCH10R25Y
UTPCH10SL25Y
UTPCH10SR25Y
UTPCH1512PP25Y
UTPCH15L25Y
UTPCH15LR25Y
UTPCH15R25Y
UTPCH15SL25Y
UTPCH15SR25Y
UTPCH2012PP25Y
UTPCH20L25Y
UTPCH20LR25Y
UTPCH20R25Y
UTPCH20SL25Y
UTPCH20SR25Y
UTPCH612PP25Y
UTPCH6L25Y
UTPCH6LR25Y
UTPCH6R25Y
UTPCH6SL25Y
UTPCH6SR25Y
UTPCH812PP25Y
UTPCH8L25Y
UTPCH8LR25Y
UTPCH8R25Y
UTPCH8SL25Y
UTPCH8SR25Y