

**CORPORATE HEADQUARTERS**

707 Dayton Road  
PO Box 1040  
Ottawa, IL 61350  
USA

p: 800-346-3119  
f: 815-433-5109

**EUROPEAN HEADQUARTERS**

Unit 10  
Westlink Commercial Park  
Oranmore, Co. Galway  
Ireland

p: + 353 91 792444  
f: + 353 91 792445

**CONEL S.R.O.**

Sokolská 71  
562 04 Ústí nad Orlicí III.  
Czech Republic

p: +420 465 521 020  
f: +420 464 647 299

**CALIFORNIA OFFICE**

Suite #210  
25531 Commercentre Dr.  
Lake Forest, CA 92630  
USA

p: 949-465-3000  
f: 949-465-3020

## EOL EIR608-series

6/19/2017

Part Number	Description
EIR608-2SFP	Managed 6 port Switch w/ 2 Gig combo ports (SFP or copper)
EIR608-4SFP	Managed 6 port Switch w/ 4 Gig combo ports (SFP or copper)

Advantech B+B SmartWorx announces the end-of-life for the products listed in the table. The EIR-608 Series has limited stock available, and customers may place orders until stock is no longer available.

The EIR608- series is facing End of Life. The reason is a chip is no longer available to manufacture the switches, and there is no exact replacement.

### Product Migration Path:

Recommended product replacement: SE510-2SFP-T, 8 port 10/100 with 2 Gig combo ports or SE512-4SFP-T, 8 port 10/100 with 2 Gig combo ports; both offer extended temperature as well.

If you have any questions, please contact [support@advantech-bb.com](mailto:support@advantech-bb.com)

Thank You,

Susan Stanley, Training Manager, Network Infrastructure  
[ssstanley@advantech-bb.com](mailto:sstanley@advantech-bb.com)