

**EVERLIGHT Electronics Co., Ltd.**

Attn: No.6-8, Zhonghua Road, Shulin Dist., New Taipei City, 23860, Taiwan

PHONE: 886 2 2685 6688

(各廠自行填寫實際電話)

FAX: 886-2-2685-6880

(各廠自行填寫實際傳真)

 **PRODUCT/PROCESS CHANGE NOTIFICATION** **PRODUCT TERMINATION NOTIFICATION(※2)****PTN tracking number: CCBU20151022-3****DATE: 10/22/2015****Contact:** Golden**Phone:** 886-2-2685-6688 ext: 6514**Title:** PM**Fax:** 886-2-2685-6689**E-mail:** goldencheng@everlight.com**Mobile:** N/A**Product influenced:**  **Major change**  **Minor change****Product Identification: (e.g., affected supplier part number(s), affected product lines including specific package types, product family):**

Lamp type.( Affected P/N, please find attached)

**Customer part number(s) (optional, if not required per agreed to customer criteria):**

N/A.

**Method, if applicable, of identifying changed product:**

N/A

**Reason for change(s):**

- Products Package Outline Dimension
- Electrical/Optical Specification
- Material
- Equipment
- Data Sheet
- Packing
- Other

**Detailed description:**

"因支架廠商無法生產此物料，故作機種宣告終止。  
Due to no production plan from leadframe, we would like to inform affected P/N EOL."  
影響機種如附件。  
Find affected P/N in attached file.

**Anticipated (positive and negative) impact on form, fit, function, quality or reliability:**

N/A

**Supplier Qualification plan schedule and/or results, where applicable:**

N/A

**EVERLIGHT Electronics Co., Ltd.**

Attn: No.6-8, Zhonghua Road, Shulin Dist., New Taipei City, 23860, Taiwan

PHONE: 886 2 2685 6688

(各廠自行填寫實際電話)

FAX: 886-2-2685-6880

(各廠自行填寫實際傳真)

**Forecasted key milestones****Date(mm/dd/yy)****Execution date.**

5/1/2016

**LTB**

2/1/2016

**Customer acknowledgement of receipt within 30 days of delivery of the PCN:****Customer:** **Approval for shipments before effective date****Name/Date:****E-mail/Address:****Title:****Phone/Fax:****Customer Comments:****EVERLIGHT acknowledgement of receipt:****RECORD BY:****DATE:**

- 1. The document of individual PCN information will be retained for a minimum of 5 years**
- 2. When the product to terminate production, check  PRODUCT TERMINATION NOTIFICATION.**

## PCN CCBU20151022 Affected Items

1363-2SURC/S530-A3  
1363-2SURC/S530-A6  
1363-2UGC(L)  
1363-2USOC/S400-Z(L)  
1363-2UYC/S400(L)  
1363-2UYC/S530-A2  
1363URC-3  
1364-15UTC/S400-X9  
363-2SURC/S530-A3  
363-2SURD/S530-A3  
363-2SURD/S530-A3(D)  
363-2SYGD/S530-E2(D)  
363-2UYD/S530-A3  
363SURD/S530-A3  
363SYGD/S530-E2  
363UYD/S530-A3  
363UYD/S530-A3-L(D)  
363VGD  
363VRC  
363VRD  
363VYD  
393-2SDRW/S530-A3  
393-2SURD/S530-A3  
393-2SURD/S530-A3(D)  
393-2SYGD/S530-E2  
393SYGD/S530-E2  
393UYD/S530-A3  
573GD  
573SDRD/S530-A3  
573SURC/S530-A3  
573SURD/S530-A3  
573SYGC/S530-E2  
573SYGD/S530-E2  
574GVD/S530-E3  
579-3SURUYC/S530-A3/R2  
HLMP0300  
HLMP0301  
HLMP0503  
HLMP0504  
MV9101