

Global Change Notification (GCN)

Product Family	TDP Plug	10717419	
		GCN Number	
Series	Multiple	September 22, 2015	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	This letter is to inform you that Molex is adding ribs to the main body housing to tighten the fit of the housing to the metal shell and of the housing to the overmolded terminal "sticks". This will reduce the positional limits of the plug blade tips. The changed parts can continue to be used the same way as they were before.		
	These 4 ribs are ali	or locking in component locations	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes		
Assessment Of Change (How Product Will Be Qualified & Validated)	Product will be qualified.		
Internal Molex Qualification Date (Planned Date Information Available)	October 09, 2015		
Sample Availability Date (Changed Part)	October 11, 2015		
Date of Implementation	October 23, 2015		
Method of Identifying Change	Lot Number		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com