



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000967I

DATE: 16-Apr-2019

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS2465Q+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	DS2465Q+U	N/A			Part reactivated from prior notice: M000965I
Reactivation	DS28EL15X-S+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX6630MUT+T	N/A			Part reactivated from prior notice: M000965I
Lead-Free Conversion	MAX1037EKA	MAX1037EKA+	15-Jul-2019	15-Jul-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1117EKA-T	MAX1117EKA+T	15-Jul-2019	15-Jul-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1118EKA	MAX1118EKA+	15-Jul-2019	15-Jul-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX3002EBP	MAX3002EBP+	15-Jul-2019	15-Jul-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX3355EEBC	MAX3355EEBC+	15-Jul-2019	15-Jul-2019	Part is leaded. Request information on lead-free version
Discontinuance	MAX1683EUK+G52	MAX1683EUK+	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX1683EUK+TG52	MAX1683EUK+T	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX17859GCB/V+	MAX17859ACB/V+CQP	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX17859GCB/V+T	MAX17859ACB/V+TCQP	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX20081WATN/V+T	MAX20081WAGN/VY+	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX2654EXT-T	N/A	15-Jul-2019	15-Jul-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX829EUK+G52	MAX829EUK+	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX829EUK+TG52	MAX829EUK+T	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX8630XETD20+G29	MAX8630XETD20+	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX8630XETD20+TG29	MAX8630XETD20+T	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured
Discontinuance	VT266BWFQX-ADJ	N/A	15-Jul-2019	15-Jul-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 17-May-2019