

## **Enclustra - Product Change Notification (PCN)**

No.:	PCN_SP_2021-017
Date:	08.12.2021

Affected Products	
Product Series	Mercury+ PE1
Affected Product Model	ME-PE1-300-W ME-PE1-400-W
Affected Parts	[EN103081] ME-PE1-300-W-R4.6 [EN103082] ME-PE1-400-W-R4.6
Replacement Parts	[EN104220] ME-PE1-300-W-R4.7 [EN104221] ME-PE1-400-W-R4.7

Type of PCN, Description and expected impact for customers		
	A – Post on Enclustra Website	
Type of PCN	☐ Removal of Product Model (if no customer is affected)	
	☐ Minor Revision without impact on customer	
	☐ Other, specify:	
	B – Inform current customers	
	☐ Increase of minimum order quantity (MOQ)	
	☐ Status Changes to end-of-life (EOL)	
	☐ Removal of Product Model (if customer is affected)	
	☐ Major Revision roll-out	
	☑ Minor Revision with impact for customer	
	☐ Other, specify:	
	C – Inform all affected customers	
	☐ Security related bug / Major non-conformance to specification	
	☐ Other, specify:	
Description of change	Starting with revision 4.7 the eMMC flash is not equipped on the board anymore.	
	This part may optionally be equipped by the customer or Enclustra (against cost) if necessary for	
	the targeted application.	
	The product pricing has already been updated to reflect this change.	
December shows	No customer demand for this feature (very scarcely used component)	
Reason for change	Component sourcing difficulties resulting in unacceptable lead-time	
Expected impact on customer	After stock depletion of affected parts (R4.6), only revision 4.7 parts will be delivered.	
	Last Time Buy (LTB) date: see above	
Forecasted key milestones	Last Time buy (LTD) date. See above	

<b>Details of change</b>	
Details	Refer to "Mercury+ PE1 R4-7 Known Issues and Changes" document available on Enclustra
	download site.

## **Contact**

## Details

If you have any questions or require additional information, please contact info@enclustra.com.

Web: www.enclustra.com

Template No: ED42010-02 Page 1 of 1