



Product Change Notification

TE Connectivity

Product Change Notification: E-17-018691

PCN Date: 15-JAN-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

T9A series relay

Description of Changes

Bobbin structure optimization with adding slots to make bobbin wall thickness symmetrical and align boss location to fix frame.

Other attachments:

[T9A bobbin optimization](#)

Reason for Changes:

Product Improvement. Optimize bobbin structure to make wall thickness symmetrical and fix frame better, no any relay function affect.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

20-APR-2018

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

12-MAY-2018

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1-1419104-1 | NO | | | "T9AP1D22-18-01" | | | |
| 1-1423091-8 | NO | | | "T9AV1L12-12" | | | |
| 1419137-1 | NO | | | "T9AV2D22-24" | | | |
| 1419137-2 | NO | | | "T9AV5D22-24" | | | |
| 1423029-1 | NO | | | "T9AV5D22-22" | | | |
| 1423091-6 | NO | | | "T9AV5L12-12" | | | |
| 1423091-9 | NO | | | "T9AV1D22-12" | | | |
| 2-1423091-3 | NO | | | "T9AV1D22-48" | | | |
| 4-1393210-3 | NO | | | "T9AV1D12-12" | | | |
| 4-1393210-8 | NO | | | "T9AV5D12-24" | | | |
| 4-1419104-2 | NO | | | "T9A-V1L22-24", "T9AV1L22-24" | | | |
| 4-1419104-3 | NO | | | "T9AV5L22-24" | | | |
| 4-1419148-7 | NO | | | "T9AV1D12-9" | | | |
| 5-1419148-0 | NO | | | "T9AV1D22-24" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-1419104-1 | NO | | | "T9AP1D22-18-01" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1419137-2 | NO | | | "T9AV5D22-24" | | | |
| 1423091-9 | NO | | | "T9AV1D22-12" | | | |
| 4-1393210-3 | NO | | | "T9AV1D12-12" | | | |
| 4-1419104-3 | NO | | | "T9AV5L22-24" | | | |
| 4-1419148-7 | NO | | | "T9AV1D12-9" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1419137-2 | NO | | | "T9AV5D22-24" | | | |
| 1423029-1 | NO | | | "T9AV5D22-22" | | | |
| 1423091-9 | NO | | | "T9AV1D22-12" | | | |
| 4-1393210-3 | NO | | | "T9AV1D12-12" | | | |
| 4-1393210-8 | NO | | | "T9AV5D12-24" | | | |
| 4-1419104-2 | NO | | | "T9A-V1L22-24", "T9AV1L22-24" | | | |
| 4-1419104-3 | NO | | | "T9AV5L22-24" | | | |
| 4-1419148-7 | NO | | | "T9AV1D12-9" | | | |
| 5-1419148-0 | NO | | | "T9AV1D22-24" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1-1423091-8 | NO | | | "T9AV1L12-12" | | | |
| 1423029-1 | NO | | | "T9AV5D22-22" | | | |
| 4-1419104-2 | NO | | | "T9A-V1L22-24", "T9AV1L22-24" | | | |
| 5-1419148-0 | NO | | | "T9AV1D22-24" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1-1419104-1 | NO | | | "T9AP1D22-18-01" | | | |
| 1423029-1 | NO | | | "T9AV5D22-22" | | | |
| 4-1393210-8 | NO | | | "T9AV5D12-24" | | | |
| 4-1419104-2 | NO | | | "T9A-V1L22-24", "T9AV1L22-24" | | | |
| 4-1419148-7 | NO | | | "T9AV1D12-9" | | | |
| 5-1419148-0 | NO | | | "T9AV1D22-24" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-1423091-8 | NO | | | "T9AV1L12-12" | | | |
| 1419137-1 | NO | | | "T9AV2D22-24" | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1423029-1 | NO | | | "T9AV5D22-22" | | | |
| 1423091-6 | NO | | | "T9AV5L12-12" | | | |
| 2-1423091-3 | NO | | | "T9AV1D22-48" | | | |
| 4-1393210-8 | NO | | | "T9AV5D12-24" | | | |
| 4-1419104-2 | NO | | | "T9A-V1L22-24", "T9AV1L22-24" | | | |
| 4-1419104-3 | NO | | | "T9AV5L22-24" | | | |
| 4-1419148-7 | NO | | | "T9AV1D12-9" | | | |
| 5-1419148-0 | NO | | | "T9AV1D22-24" | | | |