

Product Change Notification

TE Connectivity

Product Change Notification: P-20-018914

PCN Date: 10-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: VITA 66 KITS AND ACCESSORIES

Description of Changes

Manufacturing location change. Production of the p/n's listed below will be transferred from the current TE Connectivity manufacturing plant located in Mt. Joy, Pennsylvania, USA, to a TE Connectivity manufacturing plant located in Fairview, North Carolina, USA.

Reason for Changes: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new

following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.
Estimated Dates:

| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | |
|--|--|--|--|
| | 09-JUN-2020 | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | |
| | No Mixed Shipments | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 2102866-1 | NO | | | | | | |
| 2102866-2 | NO | | | | | | |
| 2226880-1 | NO | | | | | | |
| 2226881-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 2102866-1 | NO | | | | | | |
| 2102866-2 | NO | | | | | | |
| 2226880-1 | NO | | | | | | |
| 2226881-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 2102866-2 | NO | | | | | | |
| 2226880-1 | NO | | | | | | |
| 2226881-1 | NO | | | | | | |