



infrastructure for a connected world

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY

20191120-1

ISSUE DATE: 11/20/2019

IMPACTED REGIONS: NA

EMEA

LATAM

AP

REASON FOR CHANGE: DISCONTINUATION

OTHER

DESCRIPTION OF CHANGE: Increased maximum operating temperature on Pan-Net jack modules

Product discontinuation F6JBP5ZIB1.5MBN (Shielded Patch Cord).

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	11	20

***Important:** A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
F6JBP5ZIB1.5MBN	STP6XJBL1.5MBL/N