

# **Product Change Notification**



Product Group: Vishay Dale/February 10, 2015/PCN-DI-216-2015 Rev 0

## IHCL4040DZER470M5A Product Obsolescence

**DESCRIPTION OF CHANGE:** IHCL4040DZER470M5A is becoming obsolete. Other values in this series

are available. The 47uH value is the only part going obsolete.

**CLASSIFICATION OF CHANGE: Product Obsolescence** 

**REASON FOR CHANGE: Limited use** 

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

**PRODUCT CATAGORY: Inductors** 

PART NUMBERS/SERIES/FAMILIES AFFECTED: IHCL4040DZER470M5A

VISHAY BRAND(s): Vishay Dale

**TIME SCHEDULE:** 

Start Shipment Date: N/A Last Time Buy Date: 8/10/15

Last Time Shipment Date: 11/10/15

**SAMPLE AVAILABILITY: N/A** 

PRODUCT IDENTIFICATION: N/A

**QUALIFICATION DATA: N/A** 

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

### **CONTACT INFORMATION:**

#### The Americas

Vishay Intertechnology, Inc 1505 East Highway 50 P. O. Box 180 Yankton, South Dakota 57078 Ph: 1 605-665-9301

Ph: 1 605-665-9301 Fax: 1 605-665-1627 doug.lillie@vishay.com

#### **Europe**

Vishay Electronic GmbH Dr.-Felix-Zandman-Platz 1 95100 Selb Germany Ph: 49-9287-71-2282

Ph: 49-9287-71-2282 Fax: 49-9287-71-2496 jens.walther@vishay.com

#### Asia

Vishay Asia Pte Ltd. 25 Tampines Street 92 Keppel Building #02-00 Singapore 528877 Ph: +65-788-6668 Fax: +65-788-3383 victor.goh@vishay.com