

Product Discontinuance Notification

This is to inform you that the affected product(s) will be discontinued and requires your concurrence. This change will take effect 90 calendar days from the date of this notification.

PCN No: PDN21002

Title: PMD Products Phase Out

Issue Date: 2021/04/26

If you have any questions concerning this change, please contact:

PDN Coordinator

Name: Sunnie Lin

E-Mail: sunnie.lin@mail.ts.com.tw

Phone: +886-2-8913-1588 Ext. 2205

PDN Originator

Name : Chris Lin

E-mail: chris_lin@mail.ts.com.tw

Phone: +886-2-8913-1588 Ext. 2406

Effectivity:

Last time buy: 2021/05/31

Last shipment date: 2021/12/31

Note: Please contact your local sales if you have future requirement of the affected part numbers.

Product Category (Description):

Analog IC, LED Driver, Switching and Voltage Regulators in SOP-8, DIP-8 and TO-92 packages.

The full list products affected are listed in the "Affected Product/Package and Family" section.

Refer to Comparison Report for Details.

Before		After (Recommended Alternative)		
Ordering Code	Package	Ordering Code	Package	Datasheet Link
TS103CS RLG	SOP-8	TS103ACS RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS103ACS_E2103.pdf

TS19378CS RLG	SOP-8	TS19503CB10H RBG	MSOP-10EP	https://www.taiwansemi.com/assets/uploads/datasheet/TS19503CB10H_A2103.pdf
TS19378CS-01 RLG	SOP-8	TS19503CB10H RBG	MSOP-10EP	https://www.taiwansemi.com/assets/uploads/datasheet/TS19503CB10H_A2103.pdf
TS19377CS RLG	SOP-8	TS19503CB10H RBG	MSOP-10EP	https://www.taiwansemi.com/assets/uploads/datasheet/TS19503CB10H_A2103.pdf
TS34063CD C3	DIP-8	TS34063CS RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS34063CS_C2103.pdf
TS2950CT33 A3	TO-92	TS2951CS33 RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS2951_G15.pdf
TS2950CT33 B0	TO-92	TS2951CS33 RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS2951_G15.pdf
TS2950CT50 A3	TO-92	TS2951CS50 RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS2951_G15.pdf
TS2950CT50 B0	TO-92	TS2951CS50 RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS2951_G15.pdf
TS2950CT50 B0G	TO-92	TS2951CS50 RLG	SOP-8	https://www.taiwansemi.com/assets/uploads/datasheet/TS2951_G15.pdf

Reason of Discontinuance:

End of Life (EOL)

1. Production constraint
2. No demand

Affected Product/Package and Family:

Family	Package	Ordering Code	Recommended Ordering Code
Analog IC	SOP-8	TS103CS RLG	TS103ACS RLG
LED Driver	SOP-8	TS19378CS RLG	TS19503CB10H RBG
LED Driver	SOP-8	TS19378CS-01 RLG	TS19503CB10H RBG
LED Driver	SOP-8	TS19377CS RLG	TS19503CB10H RBG
Switching Regulator	DIP-8	TS34063CD C3	TS34063CS RLG
Voltage Regulator	TO-92	TS2950CT33 A3	TS2951CS33 RLG
Voltage Regulator	TO-92	TS2950CT33 B0	TS2951CS33 RLG
Voltage Regulator	TO-92	TS2950CT50 A3	TS2951CS50 RLG
Voltage Regulator	TO-92	TS2950CT50 B0	TS2951CS50 RLG
Voltage Regulator	TO-92	TS2950CT50 B0G	TS2951CS50 RLG