

PRODUCT END-OF-LIFE NOTIFICATION

Customer: Market	Customer part numbers affected: N/A
CTS part number: See list below	Product Description: Clock oscillator

- Product Change
 Process Change
 This change is notification only - no customer response is required.
 Please confirm acceptance by email or other written communication.

Description of Change: Discontinue the availability of the below listed CTS clock oscillator part numbers.

Reason for Change: Due to the manufacturers obsolescence of the PLL clock multiplier IC used in these products, along with their continued lack of demand, the listed CTS part numbers have reached their end-of-life.

Change from: Active and available to order

Change to: Obsolete and no longer available to order

Implementation Date: Immediate

Notes:	Part Numbers Affected by this EOL Notification	
	T9309-60M	T5323-50M
	T5723-50M	T4009-64M
	T5623-50M	T5723-50M-TL
	T5322-64M	T5623-50M-TL

Due to the PLL IC obsolescence, CTS is no longer able to support these listed part numbers. Unfortunately, CTS has no remaining inventory of the IC and is therefore unable to offer a last-time-buy.

CTS Contact: Jeff McCracken

CTS Approvals:	Product Manager:	<u>Ronen Cohen</u>	Date:	<u>January 27, 2020</u>
	Operations:	<u>Ebner Sanchez</u>	Date:	<u>January 27, 2020</u>
	Quality:	<u>Catherine Marcin</u>	Date:	<u>January 27, 2020</u>