



Issued date: 2021-03-10

Product Change Notification

Dear Customer, we want to inform you about the following changes.

If you have any questions regarding this issue, don't hesitate to contact your salesperson or our customer service team. We're happy to help you.

Type of change:					
☐ Product	□ Process	☐ Specification	⊠ End-of-life	☐ Other	
Affected item(s): Senseair Sunrise, Article Number: 006-0-0002					
Suggested replacement product(s): Senseair Sunrise, Article Number: 006-0-0007					
Reason for c	•				
- Default p	•		iμA instead of 38	μA at 8 samples and 16sec	

- measurement period in continuous mode.
- Steady state current during sampling increased to 99mA instead of 85mA.


Qualification, Validation plan and Results:

Tested and verified by Senseair.

Identification of changed item:

Software: FW rev 3.00

Hardware: PCB side of the sensor: K102-F & 195-00268



Implementation date for change:

April 2021

Last ordering date:

N/A