

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU PG	PGU	Type				
02 006	016	0000001538	See list below	POWER ENTRY MODULE W. FILTER	FKH	
02 006	016	0000001539	See list below	POWER ENTRY MODULE W. FILTER	FKI	
02 006	016	0000001540	See list below	POWER ENTRY MODULE W. FILTER	FKHD	
02 006	016	0000001541	See list below	POWER ENTRY MODULE W. FILTER	FKID	
02 006	016	0000001542	See list below	POWER ENTRY MODULE W. FILTER	FKG	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


List of part numbers affected				
4304.4001	4304.4062	4304.5021	4304.5053	4304.4053
4304.4002	4304.4063	4304.5022	4304.5061	4304.4054
4304.4003	4304.4064	4304.5023	4304.5062	4304.4055
4304.4004	4304.4065	4304.5024	4304.5063	4304.4060
4304.4005	4304.4066	4304.5025	4304.5064	4304.4061
4304.4021	4304.4067	4304.5026	4304.5065	4304.4063.02
4304.4022	4304.4068	4304.5027	4304.5067	4304.4070
4304.4023	4304.4069	4304.5029	4304.5069	4304.4071
4304.4024	4304.4076	4304.5031	4304.5073	4304.4072
4304.4025	4304.4077	4304.5036	4304.5081	4304.4073
4304.4027	4304.4078	4304.5037	4304.5082	4304.4074
4304.4028	4304.4079	4304.5038	4304.5083	4304.4075
4304.4042	4304.4081	4304.5039	4304.5084	4304.4080
4304.4043	4304.4091	4304.5041	4304.5085	4304.5030
4304.4044	4304.4092	4304.5042	4304.5086	4304.5040
4304.4045	4304.4093	4304.5043	4304.5087	4304.5050
4304.4046	4304.4094	4304.5044	4304.5089	4304.5054
4304.4047	4304.4095	4304.5045	4304.4027.01	4304.5064.01
4304.4048	4304.5001	4304.5046	4304.4030	4304.5090
4304.4049	4304.5002	4304.5047	4304.4041	
4304.4056	4304.5003	4304.5048	4304.4050	
4304.4057	4304.5004	4304.5049	4304.4051	
4304.4059	4304.5005	4304.5052	4304.4052	

2 Type of change

Packing improvement more stable box inlay.

3 Detailed description of change

Type of packing inlay changed from separators to a tray.
No change of cardboard box or packing unit.



New packing of FKH, FKI, FKHD, FKID, FKG					0118.2306	
creation date	created by	release date	released by	notification no.	revision	page
2015-09-10	buechlpj	2015-09-28	buechlpj	27949	-	1 of 2



4 Reason of change

Packing improvement.

5 Release date

The change will be rolled-out starting ww 40/2015 (Date code 1540 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form	No	No action required
Fit	No	No action required
Function	No	No action required
Production Site	No	No action required
Product Label	No	No action required
Customer Action	No	Notification only

7 Reference Documents / Attachments

Kind of document	Remarks
List of affected part numbers	FK_PCN_affected part numbers.xlsx
Data sheet FKH / FKG	http://www.schurter.com/pdf/english/typ_fkh.pdf
Data sheet FKI	http://www.schurter.com/pdf/english/typ_fki.pdf
Data sheet FKHD	http://www.schurter.com/pdf/english/typ_fkhd.pdf
Data sheet FKID	http://www.schurter.com/pdf/english/typ_fkid.pdf

New packing of FKH, FKI, FKHD, FKID, FKG					0118.2306	
creation date	created by	release date	released by	notification no.	revision	page
2015-09-10	buechspi	2015-09-28	buechspi	27949	-	2 of 2