

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20230207-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 7-Feb-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Test method documents PN614 and PN654 for Field Term Plugs and Field Cords were recently standardized to use only the shielded test cord FPS6X88TC. As such, the unshielded test cord, FP6X88TC, will be discontinued in favor of the shielded test cord.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	2	7
Old product discontinuation date*	2023	5	8

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
FP6X88TC	Direct	FPS6X88TC