



TAMURA CORPORATION OF AMERICA

1040 SOUTH ANDREASEN DRIVE, STE. 100 • PHONE: (951) 699-1270 • FAX: (951)676-9489
ESCONDIDO • CALIFORNIA • 92029

SALES INFORMATION BULLETIN



NO: SIB #2013002
TITLE: Tamura Current Sensor Part Number Changes
DATE: April 8th 2013

To: All TCA Distributors

Please note the following current sensor part number changes:

PRIOR PART NUMBER	NEW PART NUMBER	DK number
L31S050S05S	L31S050S05FS	L31S050S05S-ND
L31S100S05S	L31S100S05FS	MT7352-ND
L31S200S05S	L31S200S05FS	MT7353-ND
L31S300S05S	L31S300S05FS	L31S300S05S-ND
L31S400S05S	L31S400S05FS	L31S400S05S-ND
L31S500S05S	L31S500S05FS	MT7354-ND
L31S600S05S	L31S600S05FS	L31S600S05S-ND