## 1 Products affected

| Product hierarchy no. * |      |     | archy no. * | Part no.      | SBU                | Customer part no.            |     |
|-------------------------|------|-----|-------------|---------------|--------------------|------------------------------|-----|
| SBU PG                  | i PO | GU  | Туре        |               |                    |                              |     |
|                         |      | 063 | 0000000597  | 0031.1661     | Circuit protection | FEU fuse carrier 6.3x32 IP40 | n/a |
|                         |      |     |             | 0031.1666     |                    | FEU fuse carrier 6.3x32 IP40 | n/a |
|                         |      |     |             | 0031.1661.G   |                    | FEU fuse carrier 6.3x32 IP40 | n/a |
|                         |      |     |             | 0031.1666.G   |                    | FEU fuse carrier 6.3x32 IP40 | n/a |
|                         |      |     | 000000604   | 0031.3555     |                    | FAB fuse carrier 5x20 IP40   | n/a |
| 01 00                   | 02 0 |     |             | 0031.3555.G   |                    | FAB fuse carrier 5x20 IP40   | n/a |
|                         |      |     |             | 0031.3555.D   |                    | FAB fuse carrier 5x20 IP40   | n/a |
|                         |      |     |             | 0031.9826     |                    | FAF fuse carrier 5x20 IP40   | n/a |
|                         |      |     |             | 0031.3562.1   |                    | FEK fuse carrier 5x20 IP54   | n/a |
|                         |      |     |             | 0031.3562.1.G | ]                  | FEK fuse carrier 5x20 IP54   | n/a |
|                         |      |     |             | 0031.3562     |                    | FEK fuse carrier 5x20 IP54   | n/a |

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

#### 2 Type of change


New location of final assembly and new country of origin of various fuse holder parts.

#### 3 Detailed description of change

The location of final assembly and the country of origin of various fuse holders change from Switzerland to Czech Republic.

| Part Number   | Old location of | New location of |     | Old country of | New country of |
|---------------|-----------------|-----------------|-----|----------------|----------------|
|               | final assembly  | final assembly  |     | origin         | origin         |
| 0031.1661     | СН              | CZ              | ] [ | СН             | CH             |
| 0031.1661.G   | CH              | CZ              |     | СН             | CH             |
| 0031.1666     | CH              | CZ              |     | СН             | CH             |
| 0031.1666.G   | CH              | CZ              |     | СН             | СН             |
| 0031.3555     | CH              | CZ              |     | СН             | СН             |
| 0031.3555.G   | CH              | CZ              |     | СН             | СН             |
| 0301.3562     | CH              | CZ              |     | СН             | CZ             |
| 0031.3562.1   | CH              | CZ              |     | СН             | CZ             |
| 0031.3562.1.G | СН              | CZ              | ] [ | СН             | CZ             |
| 0031.9826     | СН              | CZ              | ] [ | СН             | СН             |

Label adjustment:



|   | Product Change Notification |               |              |             |                 |     | Relocation of production |             |  |
|---|-----------------------------|---------------|--------------|-------------|-----------------|-----|--------------------------|-------------|--|
|   | owner                       | creation date | release date | released by | change order no | rev | page                     | D10 002 014 |  |
| [ | dislercy                    | 2016-05-04    | 2016-06-09   | bergerra    | 2009947         | A   | 1 of 2                   | D10-003-914 |  |

## 4 Reason of change

Reorganization of production process.

#### 5 Release date

The change will be rolled-out starting ww 23/2016 and lasts approx. 5 months depending on the variant.

# 6 Impact of change and recommended action

| Form            | No  | There are no form changes  |
|-----------------|-----|--|
| Fit             | No  | There are dimensional changes  |
| Function        | No  | This is a non-functional change  |
| Production Site | Yes | Relocation of final assembly from CH to CZ   |
| Product Label   | Yes | Adjustment of the label if the location of final assembly and/or the country of origin changes |
| Customer Action | No  | Notification only  |

### 7 Reference Documents / Attachments

| Kind of document | Remarks                         |
|------------------|---------------------------------|
| Data sheet       | for Fuse holder type FEU        |
| Data sheet       | for Fuse holder type FAU        |
| Data sheet       | for Fuse holder type FAC        |
| Data sheet       | for Fuse holder type FAB        |
| Data sheet       | for Fuse holder type FAF        |
| Data sheet       | for Fuse holder type FEF        |
| Data sheet       | for Fuse holder type FEF (snap) |

| Product Change Notification |               |              |             |                 |     | Relocation of production |             |  |
|-----------------------------|---------------|--------------|-------------|-----------------|-----|--------------------------|-------------|--|
| owner                       | creation date | release date | released by | change order no | rev | page                     | D10 002 011 |  |
| dislercy                    | 2016-05-04    | 2016-06-09   | bergerra    | 2009947         | A   | 2 of 2                   | D10-003-914 |  |