

Product Termination Notification



Product Group: Opto Modules & Visibles 18-APR-2019 / PTN OMV-1071-2019 Rev. 0

TITLE: Product Discontinuation of low running 7-segment displays

Discontinuation of TDSL3150-G, TDSL5150-GH, TDSL5160-GH, TDSO5150-**DESCRIPTION OF CHANGE:** M. Recommended alternatives, where available, are listed in the file:

"Alternative_Types_PTN-OMV-1071-2019.htm"

Product Obsolescence CLASSIFICATION OF CHANGE:

Displays

REASON FOR CHANGE:

The declining demand for these special selection types in the market along with the obsolescence of the constrained chip specifications makes this

series no longer feasible to manufacture.

PRODUCT CATEGORY:

PART NUMBERS / SERIES / FAMILIES AFFECTED:

TDSL3150-G TDSL5150-GH TDSL5160-GH TDSO5150-M

VISHAY BRAND(s):

VISHAY SEMICONDUCTORS

TIME SCHEDULE:

Annotations about time schedule:

18-OCT-2019 Last Time Buy Date: Last Time Shipment Date: 17-APR-2020

SAMPLES AVAILABLE BEGINNING:

We need samples of replacement parts for evaluation: □Yes □No If Yes return this form to contact information below.

This PCN is considered approved, without further notification, unless we receive specific customer concerns before: 18-JUL-2019 or as specified by contract.

ISSUED BY:

PM: Harald Lunt, Product Marketing Visibles

Phone: +49 7131 67-2661

Email: harald.lunt@vishay.com

For further Information, please contact your regional Vishay office.

CONTACT INFORMATION:

VISHAY Intertechnology Asia Pte. Ltd. Business Marketing Asia/Japan		VISHAY Intertechnologies, Inc. Business Marketing The Americas -	
25 Tampines Street 92		Opto	
Keppel Building # 02-00		552 Villa Centre Way	
Singapore 528877		San Jose, CA 95128 5136	
Phone:	+65 6780 7879	USA	
Fax:	+65 6780 7897	Phone:	+1-408-567-8358
		Fax:	+1 408-240-5687

VISHAY Semiconductor GmbH Business Marketing Europe Opto Theresienstr. 2 D-74025 Heilbronn Germany Phone: +49-7131-67-2113 +49-7131-67-3144 Fax:

obsolete type acc.	alternative type	
PTN-OMV-1071-2019		
TDSL3150-G	TDSL3150	
TDSL5150-GH	TDSL5150-FG	
TDSL5160-GH	TDSL5160	
TDSO5150-M	TDSO5150-LM	