

6/22/2021

Subject: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type (Only Checked Changes Apply)			
□ Production/assembly location		☐ Material	☐ End of Life w/ replacement
☐ Part Number/Ordering Code		☐ Packaging	☐ End of Life w/o replacement
☐ Country of Origin		☐ Point of Purchase	☐ Additional tool/refurbishment
☐ Design (fit, form, function)		☐ Point of Pick up	☐ Cost/Lead Time
☐ Engineering record (non-fit, form, f	function)	☐ Supply Chain	☐ Process
Additional Information			
From: To:			
HT Order Code: 111-01196, T255R0HIRX2 HT Order Code: 111-01196, T255R0HIRX2			
Country of Origin: Milwaukee, WI		Country of Origin: Monterrey, MX	
Production Location: Milwaukee, WI		Production Location: Monterrey, MX	
Scope			
HT PN / Ordering Code	Customer PN		Change Effective*
111-01196, T255R0HIRX2	1436-2238-ND, 1436-1455-ND		9/10/2021

We ask that you please acknowledge this notification by 7/16/2021, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Dylan Goetzke

Quality Project Administrator Office: 414 355 1130 x 8751

Email: dylan.goetzke@htamericas.com

^{*}Effective date is subject to change based on availability