

Global Change Notification (GCN)

Product Family	SFP	10624041
		GCN Number
Series	74441	January 17, 2014
		Date Issued
Reason For Change	Manufacturing Process Change	
Change Description	This letter is to inform you that we are removing lubrication from the connector plating process for part number 744410021 which will be replaced by the non-lubricated part number 744410031. We will also be moving production to our manufacturing facility in Chengdu, China due to increase in demand. Removing the lubrication from our process will not affect the form, fit, or function of the connector.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)		
Internal Molex Qualification Date (Planned Date Information Available)	December 31, 2013	
Sample Availability Date (Changed Part)	December 31, 2013	
Date of Implementation	February 17, 2014	
Method of Identifying Change	label	
Recommended Replacement Parts	74441-0031	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		